

Industrial Automation

(Automação de Processos Industriais)

CAD/CAM and CNC

<http://users.isr.ist.utl.pt/~jag/courses/api1213/api1213.html>

Slides 2010/2011 Prof. Paulo Jorge Oliveira
Rev. 2011-2013 Prof. José Gaspar

Syllabus:

Chap. 4 - GRAFCET (*Sequential Function Chart*) [1 weeks]

...

Chap. 5 – CAD/CAM and CNC [1 week]

Methodology CAD/CAM. Types of CNC machines.

Interpolation for trajectory generation.

Integration in Flexible Fabrication Cells.

...

Chap. 6 – Discrete Event Systems [2 weeks]

Some pointers to CAD/CAM and CNC

History: <http://users.bergen.org/jdefalco/CNC/history.html>


Tutorial: <http://users.bergen.org/jdefalco/CNC/index.html>
<http://www-me.mit.edu/Lectures/MachineTools/outline.html>
<http://www.tarleton.edu/~gmollick/3503/lectures.htm>

Editors (CAD): <http://www.cncezpro.com/>
<http://www.cadstd.com/>
<http://www.turbocad.com>
<http://www.deskam.com/>
<http://www.cadopia.com/>

Bibliography:

- * **Computer Control of Manufacturing Systems**, Yoram Koren, McGraw Hill, 1986.
- * **The CNC Workbook : An Introduction to Computer Numerical Control** by Frank Nanfarra, et al.

CAD/CAM and CNC



Concept



Tool / Methodology





Prototype

*Nowadays, the machines work perfectly OK! the technological question is mostly about **integration**.*

CAD/CAM and CNC at home!

*Order in the internet,
receive by mail and
assemble yourself!*
<http://www.ultimaker.com/>



The screenshot shows the Cura 12.08 software interface. At the top, there are tabs for File, Simple, Expert, Help, Print config (selected), Advanced config, and Start/End-GCode. Below these are sections for Accuracy, Speed & Temperature, Support, and Filament. A 3D view of a Yoda bust is shown in the center, positioned on a grid. The bottom of the screen displays slicing parameters: Layer height (mm) 0.1, Wall thickness (mm) .8, Print speed (mm/s) 50, Printing temperature 210, Support type Everywhere, Add raft unchecked, Bottom/Top thickness (mm) 0.6, Fill Density (%) 20, Line count 1, Start distance (mm) 3.0, Diameter (mm) 2.865, and Packing Density 1.00. At the bottom, there are buttons for Load Model, Slice to GCode, Print GCode, Show Log, Open file location, To SDCard, and Show result.

Load Model Slice to GCode Print GCode

File Simple Expert Help

Print config Advanced config Start/End-GCode

Accuracy

Layer height (mm) 0.1

Wall thickness (mm) .8

Fill

Bottom/Top thickness (mm) 0.6

Fill Density (%) 20

Skirt

Line count 1

Start distance (mm) 3.0

Speed & Temperature

Print speed (mm/s) 50

Printing temperature 210

Support

Support type Everywhere

Add raft

Filament

Diameter (mm) 2.865

Packing Density 1.00

3D Top

Yoda.stl

4g Print time: 01:16 Cost: 0.37

Show Log Open file location To SDCard Show result

Brief relevant history

NC

1947 – US Air Force needs lead John Parsons to develop a machine able to produce parts described in 3D.

1949 – Contract with *Parsons Corporation* to implement proposed method.

1952 – Demonstration at MIT of a working machine tool (NC), able to produce parts resorting to simultaneous interpolation on several axes.

1955 – First NC machine tools reach the market.

1957 - NC starts to be accepted as a solution in industrial applications , with first machines starting to produce.

197x – Profiting from the microprocessor invention appears the CNC.

Evolution in brief

CAD/CAM and CNC

- Modification of existing machine tools with **motion sensors** and **automatic advance** systems.
- Close-loop control systems for **axis control**.
- Incorporation of the **computational advances** in the CNC machines.
- Development of **high accuracy interpolation** algorithms to trajectory interpolation.
- Resort to **CAD systems to design parts** and to manage the use of CNC machines.

CAD/CAM and CNC

Objectives

- To augment the accuracy, reliability, and the ability to introduce changes/new designs
- To augment the workload
- To reduce production costs
- To reduce waste due to errors and other human factors
- To carry out complex tasks (e.g. Simultaneous 3D interpolation)
- Augment precision of the produced parts.

Advantages

- Reduce the production/delivery **time**
- Reduce **costs** associated to parts and other auxiliary
- Reduce **storage** space
- Reduce time to start production
- Reduce machining time
- Reduce time to market (on the design/redesign and production).

Limitations:

- High initial **investment** (30k€ to 1500k€)
- Specialized **maintenance** required
- Does not eliminates the human errors completely
- Requires more specialized **operators**
- Not so relevant the advantages on the production of small or very small series.

CAD/CAM and CNC

Methodology CAD/CAM

To use technical data from a database in the design and production stages. Information on parts, materials, tools, and machines are integrated.


CAD (Computer Aided Design)


Allows the design in a computer environment.

CAM (Computer Aided Manufacturing)

To manage programs and production stages on a computer.


CAD/CAM and CNC Methodology CAD/CAM





CAD/CAM and CNC



Tools:



CAD/CAM and CNC

Tools:



**Attention to the constraints
on the materials used!...**



- Speed of advance
- Speed of rotation
- Type of tool

CAD/CAM and CNC

Tools:



FACING



ROUGHING



FINISHING



ROUND NOSE



FINISHING



ROUGHING



FACING


LEFT-CUT TOOLS

RIGHT-CUT TOOLS

Specific tools to perform different operations.



CAD/CAM and CNC

Tools: impact on the quality of finishing (μm)



CAD/CAM and CNC

Evolution of tools performance:



CAD/CAM and CNC

Industrial areas of application:

- Aerospace
- Machinery
- Electricity (board production)
- Automobiles
- Instrumentation
- Moulds

CAD/CAM and CNC

Evolution of Numerical Control

- Numerical Control (NC)
 - Data on paper or received in serial port
 - NC machine unable to perform computations
 - Hardware interpolation

- Direct Numerical Control (DNC)
 - Central computer control a number of machines DNC or CNC

- Computer Numerical control (CNC)
 - A computer is on the core of each machine tool
 - Computation and interpolation algorithms run on the machine

- Distributive numerical control
 - scheduling
 - Quality control
 - Remote monitoring




CAD/CAM and CNC


Numeric Control

Architecture of a NC system: 1 axis

Open-loop




Closed-loop




CAD/CAM and CNC

Numeric Control

Architecture of a NC system: 3 axis




Open-Loop-System



Closed-Loop-System

CAD/CAM and CNC

Interpolation Motivation



Note 1: The references are usually very simple, e.g. $Z_i(t)=a_i t + b_i$,

*Note 2: Step motors count steps, i.e. are numerical integrators
hence we have to convert $Z(t)$ to an incremental representation p_k*

CAD/CAM and CNC

Interpolation: use incremental representation

Motivation from numerical integration

Area of a function

$$z(t) = \int_0^t p(\tau) d\tau \cong \sum_{i=1}^k p_i \Delta t$$

Introducing z_k , as the value of z at $t=k\Delta t$


$$z_k = \sum_{i=1}^{k-1} p_i \Delta t + p_k \Delta t = z_{k-1} + \Delta z_k, \quad \Delta z_k = p_k \Delta t \quad \Rightarrow \quad p_k = \Delta z_k / \Delta t$$

The integrator works at a rhythm of $f=1/\Delta t$ and the function p is given app. by:

$$p_k = p_{k-1} \pm \Delta p_k$$

To be able to implement the integrator in registers with n bits, p must verify $p_k < 2^n$.

In the following we will use p_k and Δp_k instead of z_k or $z(t)$.



CAD/CAM and CNC

Implementation of a Digital Differential Analyzer (DDA)

The p register input is 0, $+1 = \Delta p$ or $-1 = -\Delta p$.

The q register stores the **area integration** value


$$q_k = q_{k-1} + p_k.$$

If the q register value exceeds $(2^n - 1)$ an overflow occurs and $\Delta z = 1$:

$$\Delta z_k = 2^{-n} p_k$$


Defining $C = f/2^n$, and given that $f = 1/\Delta t$, one has a scale factor from p_k to Δz_k :

$$\Delta z_k = C p_k \Delta t$$




CAD/CAM and CNC

DDA for Linear Interpolation (1 axis):




Let $p=5$, $\Delta p=0$ and
assume q is a 3 bits register

Step	q	Δz	$\Sigma \Delta z$
1	5		0
2	2	1	1
3	7	1	1
4	4	1	2
5	1	1	3
6	6		3
7	3	1	4
8	0	1	5
9	5		5
		...	





$$f_0 = \left(\frac{\Delta z}{\Delta t} \right)_k = C p_k, \quad \text{where} \quad C = \frac{f}{2^n}$$



CAD/CAM and CNC



DDA for Linear Interpolation (2 axis):



(a) Specifications

(b) DDA solution

(c) Results



CAD/CAM and CNC

Exponential Deacceleration:


Let $p(t) = p_0 e^{-\alpha t}$ and $\frac{\Delta z}{\Delta t} = Cp_k = Cp_0 e^{-\alpha t}$.

The differential of $p(t)$ is approximate


$$-\Delta p = \alpha p_k \Delta t$$

Setting $C=\alpha$, i.e. $f=2^n\alpha$, one has

$$-\Delta p = \Delta z$$



Example: $p(t)=15e^{-t}$



CAD/CAM and CNC

Circular Interpolation:

Let $(X - R)^2 + Y^2 = R^2$ or


$$X = R(1 - \cos(\omega t))$$

$$Y = R \sin(\omega t)$$


The differential is

$$dX = \omega R \sin(\omega t) dt = d(-R \cos(\omega t))$$

$$dY = \omega R \cos(\omega t) dt = d(R \sin(\omega t))$$




Example: Circumference of radius 15, centered at the origin.




CAD/CAM and CNC **Full DDA**

2D Line, 2D Arc, Acceleration / Deacceleration




CAD/CAM and CNC

CNC Axes Control



Dynamics of a control loop





CAD/CAM and CNC

CNC Programming

Steps to execute a part

A) Read/interpret the technical drawings



CAD/CAM and CNC

CNC Programming

B) Choice of the most adequate **machine-tool** for the several stages of machining

Relevant features:

- The **workspace** of a machine versus the part to be produced
- The options available on each machine
- The **tools available**
- The mounting and the part handling
- The operations that each machine can perform

C) Choice of the most adequate **tools**

Relevant features:

- The **material** to be machined and its characteristics
- Standard tools cost less
- The quality of the mounting part is function of the number of parts to produce
- Use the **right tool** for the job
- Verify if there are backup tools and/or stored available
- Take into account tool aging

CAD/CAM and CNC

CNC Programming

Approximate Energy Requirements in Cutting Operations (at drive motor, corrected for 80% efficiency; multiply by 1.25 for dull tools).

Material	Specific energy W · s/mm ³	hp · min/in. ³
Aluminum alloys	0.4–1.1	0.15–0.4
Cast irons	1.6–5.5	0.6–2.0
Copper alloys	1.4–3.3	0.5–1.2
High-temperature alloys	3.3–8.5	1.2–3.1
Magnesium alloys	0.4–0.6	0.15–0.2
Nickel alloys	4.9–6.8	1.8–2.5
Refractory alloys	3.8–9.6	1.1–3.5
Stainless steels	3.0–5.2	1.1–1.9
Steels	2.7–9.3	1.0–3.4

CAD/CAM and CNC

CNC Programming

D) Cutting data

- Spindle Speed – speed of rotation of the cutting tool (rpm)

Feedrate – linear velocity of advance to machine the part (mm/minute)

- Depth of Cut – depth of machining in z (mm)

E) Choice of the interpolation plane, in 2D ½ machines



CAD/CAM and CNC

CNC Programming

F₁) Unit system

imperial –inches (**G70**) or international millimeters (**G71**).

F₂) Command mode*

Absolute – relative to world coordinate system (**G90**)

Relative – movement relative to the actual position (**G91**)

* There are other command modes, e.g. helicoidal.

CAD/CAM and CNC

CNC Programming

G) MANUAL DATA INPUT

N	Sequence Number
G	Preparatory Functions
X	X Axis Command
Y	Y Axis Command
Z	Z Axis Command
R	Radius from specified center
A	Angle ccw from +X vector
I	X axis arc center offset
J	Y axis arc center offset
K	Z axis arc center offset
F	Feedrate
S	Spindle speed
T	Tool number
M	Miscellaneous function

CAD/CAM and CNC

Example of a CNC program

N30 G0 T1 M6

N35 S2037 M3

N40 G0 G2 X6.32 Y-0.9267 M8

N45 Z1.1

N50 Z0.12

N55 G1 Z0. F91.7

N60 X-2.82

N65 Y0.9467


N70 X6.32

N75 Y2.82


N80 X-2.82

N85 G0 Z1.1

...




Unregistered HyperCam




CAD/CAM and CNC

Preparatory functions (inc.)


G00 – GO




G01 – Linear Interpolation



G02 – Circular Interpolation (CW)




G03 – Circular Interpolation (CCW)




CAD/CAM and CNC

Preparatory functions (inc.)


G00 – GO




G01 – Linear Interpolation



G02 – Circular Interpolation (CW)




G03 – Circular Interpolation (CCW)



CAD/CAM and CNC


Canned Cycles

G81 – Drilling cycle with multiple holes



Special Cycles or Canned Cycles

G78 – Rectangular pocket cycle, used to clean a square shaped area



CAD/CAM and CNC

Other preparatory functions

- G04 - A temporary dwell, or **delay** in tool motion.
- G05 - A permanent hold, or **stopping** of tool motion. It is canceled by the machine operator.
- G22 - Activation of the stored **axis travel limits**, which are used to establish a safety boundary.
- G23 - Deactivation of the stored axis travel limits.
- G27 - Return to the machine **home** position via a programmed intermediate point
- G34 - Thread cutting with an increasing lead.
- G35 - Thread cutting with a decreasing lead.
- G40 - Cancellation of any previously programmed tool radius compensation
- G42 - Application of cutter radius compensation to the right of the workpiece with respect to the direction of tool travel.
- G43 - Activation of tool length compensation in the same direction of the offset value
- G71 - Canned cycle for multiple-pass turning on a lathe (foreign-made)
- ...

CAD/CAM and CNC

Miscellaneous functions

- M02 - Program end
- M03 - Start of spindle rotation clockwise
- M04 - Start of spindle rotation counterclockwise
- M07 - Start of mist coolant
- M08 - Start of flood coolant

CAD/CAM and CNC

Tool change




Note: should be of easy access, when performed manually.

CAD/CAM and CNC


Example of CNC programming

See <http://www.ezcam.com/web/tour/tour.htm>



CAD/CAM and CNC

Example of CNC programming



CAD/CAM and CNC

Advanced CNC programming languages

- Automatically Program Tool (APT)
Developed at MIT in 1954
- Derived from APT:
 - ADAPT (IBM)
 - IFAPT (France)
 - MINIAPT (Germany)
- Compact II
- Autospot
- SPLIT

CAD/CAM and CNC

Machine operation


Rules of Security

- Security is essential!
- The eyes must be always protected.
- The tools and parts must be handled and installed properly.
- Avoid the use of large cloths
- Clean the parts with a brush. Never with the hands.
- Be careful with you and the others.

CAD/CAM and CNC

Machine operation

Verify tolerances and tools offsets for proper operation




CAD/CAM and CNC

Machine operation


Load program

Follow up machine operation

Verify carefully the produced part.




CAD/CAM and CNC at home!



```
;TYPE:CUSTOM
M92 E865.888000
M109 S210.000000
;Sliced /home/ricardo/tmp/dump_body.stl at: Sun 28 Oct 2012 22:20:23
;Basic settings: Layer height: 0.1 Walls: 0.8 Fill: 20
;Print time: 1:16
;Filament used: 1.10m 9.24g
;Filament cost: 0.37
G21 ;metric values
G90 ;absolute positioning
M107 ;start with the fan off
G28 X0 Y0 ;move X/Y to min endstops
G28 Z0 ;move Z to min endstops
G92 X0 Y0 Z0 E0 ;reset software position to front/left/z=0.0
G1 Z15.0 F180
G92 E0 ;zero the extruded length
G1 F200 E3
G92 E0 ;zero the extruded length again
;G1 X100 Y100 F9000
G1 F9000
;LAYER:0
;TYPE:SKIRT
G1 X74.244 Y116.715 Z0.3 F9000.0
G1 F4200.0
G1 E4.525
G1 F9000.0
G1 X75.623 Y120.052 Z0.3 F1200.0 E4.5922
G1 X113.604 Y120.572 E5.2993
```

CAD/CAM and CNC at home!



<https://github.com/bkubicek/Marlin>

http://wiki.ultimaker.com/How_to_upload_new_firmware_to_the_motherboard

```
// Implemented Codes
//-----
// G0 -> G1
// G1 - Coordinated Movement X Y Z E
// G4 - Dwell S<seconds> or P<milliseconds>
// G28 - Home all Axis
// G90 - Use Absolute Coordinates
// G91 - Use Relative Coordinates
// G92 - Set current position to coordinates given

// RepRap M Codes
// M104 - Set extruder target temp
// M105 - Read current temp
// M106 - Fan on
// M107 - Fan off
// M109 - Wait for extruder current temp to reach target temp.
// M114 - Display current position

// Custom M Codes
// M80 - Turn on Power Supply
// M20 - List SD card
// M21 - Init SD card
// M22 - Release SD card
// M23 - Select SD file (M23 filename.g)
// M24 - Start/resume SD print
// M25 - Pause SD print
```

CAD/CAM and CNC at home!

```

Marlin | Arduino 0022
File Edit Sketch Tools Help
Marlin $ Configuration.h EEPROM.h FatStructs.h Marlin.h [2C]
void loop()
{
    if(buflen<3)
        get_command();
        checkautostart(false);
    if(buflen)
    {
        process_commands();
        buflen = (buflen-1);
        bufindr = (bufindr + 1)%BUFSIZE;
    }
    //check heater every n milliseconds
    manage_heater();
    manage_inactivity(1);
    LCD_STATUS;
}

inline void get_command()
{
    while( Serial.available() > 0  && buflen < BUFSIZE) {
        serial_char = Serial.read();
        if(serial_char == '\n' || serial_char == '\r' || serial_char
        {
            ...
        }
    }
}

```



```

Marlin | Arduino 0022
File Edit Sketch Tools Help
Marlin $ Configuration.h EEPROM.h FatStructs.h Marlin.h [2C]
inline void process_commands()
{
    unsigned long codenum; //throw away variable
    char *starpes = NULL;

    if(code_seen('G'))
    {
        switch((int)code_value())
        {
            case 0: // G0 -> G1
                ...
            case 1: // G1
                get_coordinates(); // For X Y Z E F
                prepare_move();
                previous_millis_cmd = millis();
                //ClearToSend();
                return;
                //break;
            case 4: // G4 dwell
                codenum = 0;
                if(code_seen('P')) codenum = code_value(); // milliseconds
                if(code_seen('S')) codenum = code_value() * 1000; // second
                codenum += millis(); // keep track of when we started wait
                while(millis() < codenum ){
                    manage_heater();
                }
        }
    }
}

```

CAD/CAM and CNC at home!

```

void prepare_move()
{
    plan_buffer_line(destination[X_AXIS], destination[Y_AXIS],
                     destination[Z_AXIS], destination[E_AXIS],
                     feedrate*feedmultiply/60.0/100.);

    for(int i=0; i < NUM_AXIS; i++) {
        current_position[i] = destination[i];
    }
}

void plan_buffer_line(float x, float y, float z, float e, float
// Add a new linear movement to the buffer.
// steps_x, _y and _z is the absolute position in mm.
// Microseconds specify how many microseconds the move should
// calculation the caller must also provide the physical length

// Calculate the buffer head after we push this byte
int next_buffer_head = (block_buffer_head + 1) %BLOCK_BUFFER

// If the buffer is full: good! That means we are well ahead
// Rest here until there is room in the buffer.
while(block_buffer_tail == next_buffer_head) {
    manage_heater();
    manage_inactivity(1);
}

// The target position of the tool in absolute steps
// Calculate target position in absolute steps
long target[4];
target[X_AXIS] = lround(x*axis_steps_per_unit[X_AXIS]);
target[Y_AXIS] = lround(y*axis_steps_per_unit[Y_AXIS]);
target[Z_AXIS] = lround(z*axis_steps_per_unit[Z_AXIS]);

```

```

ISR(TIMER1_COMPA_vect)
// "The Stepper Driver Interrupt" - This timer interrupt is the workhorse.
// It pops blocks from the block_buffer and executes them by pulsing the st
{
    if(busy){ /*Serial.println("BUSY");*/
        return;
    } // The busy-flag is used to avoid reentering this interrupt

    busy = true;
    sei(); // Re enable interrupts (normally disabled while inside an interrupt)
#endif ULTIPANEL
static int breakdown=0;
if((breakdown++)%100==0)
    buttons_check();
/* [ErikDeBruijn] Perhaps it would be nice to use a piece of code like this
   if(sdactive){
       sprintf("SD printing byte %i%",(int) (sdpos/filesize*100)); // perh
       Serial.print(sdpos);
       Serial.print("/");
       Serial.println(filesize);
   }
*/
#endif

```

CAD/CAM and CNC at home!

